

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application for:	Examiner: Vibol Tan
Sapumal Wijeratne	Art Group: 2819
Application No.: 10/769,257	Confirmation No. 8142
Filed: 01/30/2004	
Patent No.: 6,958,629 B2	
Issued: 10/25/2005	
For: A SINGLE STAGE, LEVEL RESTORE CIRCUIT WITH MIXED SIGNAL INPUTS	

Attn: Certificate of Corrections Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

Upon review of the above-referenced Letters Patent, Applicant noted errors that are the mistake of the Applicant. Those errors are as follows:

Figure 2

Reference numbers 212, 250, 252, 266, and 268 should be deleted.

Figure 3

Reference numbers 330 and 392 should be deleted.

Column 3

Lines 49-50, "...n2 160..." should read --...n2 164....

Column 4

Line 7, "...n2 160..." should read ---n2 164...--.

Line 11, "...transisters 264..." should read ---transisters 262-264....--.

Line 37, "...n1 264..." should read ---n2 264...--.

Column 5

Lines 41 and 46, "...internal node 274..." should read ---internal node 270...--.

Column 6

Lines 6 and 10, "...A2_b 322..." should read ---A2_b 332...--.

Lines 7 and 10, "...A2 320..." should read ----A2 330...--.

Column 7

Line 38, "...second large comprises..." should read ---second large signal comprises....--.

Included with this submission is a Certificate of Correction and it is respectfully requested that a Certificate of Correction be issued. This request for correction is made under the provisions of 37 CFR 1.323.

Payment by Deposit Account No. 500393 is included in the amount of \$100.00 for the fee as set forth in 37 CFR § 1.20(a).

Respectfully submitted,

SCHWABE, WILLIAMSON & WYATT, P.C.

Dated: 12/06/2006

/James J. Namiki/
James J. Namiki
Registration No. 51148

Pacwest Center, Suite 1900
1211 SW Fifth Avenue
Portland, Oregon 97204
Telephone: 503-222-9981

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 6,958,629 B2

APPLICATION NO.: 10/769,257

ISSUE DATE : 10/25/2005

INVENTOR(S) : Sapumal Wijeratne

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Figure 2
Reference numbers 212, 250, 252, 266, and 268 should be deleted.

Figure 3
Reference numbers 330 and 392 should be deleted.

Column 3
Lines 49-50, "...n2 160..." should read --...n2 164...--.

Column 4
Line 7, "...n2 160..." should read --...n2 164...--.
Line 11, "...transisters 264..." should read --...transisters 262-264...--.
Line 37, "...n1 264..." should read --...n2 264...--.

Column 5
Lines 41 and 46, "...internal node 274..." should read --...internal node 270...--.

Column 6
Lines 6 and 10, "...A2_b 322..." should read --...A2_b 332...--.
Lines 7 and 10, "...A2 320..." should read --...A2 330...--.

Column 7
Line 38, "...second large comprises..." should read --...second large signal comprises...--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

SCHWABE, WILLIAMSON & WYATT, P.C.
1211 SW Fifth Avenue, Suite 1900
Portland, OR 97204

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.